SAFETY NOTICE: UPDATE

VOLUNTARY PRODUCT RECALL OF CERTAIN LOTS OF FIBRE METAL E2 CAP AND NORTH PEAK A79 HARD HATS

Dear Valued Customer.

Reason for Recall: Honeywell has determined that additional lots of E2 may not perform to marked specifications. Honeywell is conducting a voluntary recall of certain affected hardhats which is limited to the part and specific lot numbers listed below.

Risk to Health: Although Honeywell has not received and is not aware of any reported concern regarding these hard hats, there is a potential risk that the listed hard hats will not provide the level of protection for which they were designed and certified for in case of impact.

Products Added to Recall:

- Yellow E2 product lots produced by Honeywell in April 2016
- Black E2 product lots produced by Honeywell in May 2016

Products Already on Recall:

- Gray E2 product lots produced by Honeywell in May 2016
- White E2 product lots produced by Honeywell in December 2017
- Blue E2 product lots produced by Honeywell in January 2018.
- A79 product lots from mold #4 shipped from Honeywell's distribution center between April 2016 and January 2018.

Instructions to Customers:

Please take the following actions to help us remove these items from use:

- 1.) Identify if your hard hat is one of the affected products (see attachments)
- 2.) Return the affected product back your distributor. Your distributor will provide you with a credit.
- 3.) If you have less 20 affect hard hats or are unable to provide your distributor with proof of purchase, you may choose to use the self-service website. https://form.jotform.com/e429580/honeywellhardhatregistration
- 4.) On the website, you will be instructed on how to dispose of your product and will be given a voucher in an amount that represents our manufacturer suggested list price once you confirm that you have properly destroyed and disposed of any affected product. You may then use that voucher for purchase of Honeywell Personal Protective Equipment (Fibre Metal, North, Honeywell, Howard Leight and Uvex) at participating distributors.

Enclosure

HOW TO IDENTIFY AFFECTED HARD HATS

AFFECTED LOT NUMBERS: See attached sheets

- 1. **E2** List
- 2. A79 List

LOCATING LOT NUMBERS-the below images highlight the most common locations for lot number location. Actual location may vary.

Only certain lot numbers as described here are being recalled. The affected lots of Fibre Metal E2 Cap were produced in April 2016 (Yellow E2), May 2016 (Gray and Black E2), December 2017 (White E2) and January 2018 (Blue). The lots of North Peak A79 were from mold #4 and shipped from our distribution center from April 2016 through January 2018.

There are two ways to identify affected product. 1.) if the carton is available, compare lot number on the label on the carton to the list provided on the attached.



Carton Label with Lot Number


2.) If the hard hats have already been removed from the case, the Lot Number will no longer be identifiable. In that case, look for the manufacturer's date on the underside of the brim.

Model	Color of Shell	Manufacture Date	Mold
E2	Yellow	April 2016	All
E2	Gray	May 2016	All
E2	Black	May 2016	All
E2	White	December 2017	All
E2	Blue	January 2017	All

A79	Various	April 2016 – January	Only mold #4
		2018	



a. The lots in question for North Peak A79 were produced from one of our molds (mold #4) from the period April 2016 through January 2018. Therefore, if the Lot Number is not available, return North Peak A79 hard hats with a manufacturer's date between April 2016 and January 2018 and have the mold identification number of "4".



Thank you for your urgent attention to this quality alert.

Sincerely,

Tim Wolski Product Marketing Manager Honeywell Safety Products